

Basic Vehicle Condition Guide

Report ID: 25,107,389


3 Version:

12 Dec 2024 Created:

Make: Model: Holden Acadia **Body Style:** SUV Year: 2019 Registration: MMS623 Reg Expiry: 04 Feb 2025 **WoF Expiry: Odometer: Good No:** 18 Nov 2025 115,493 Kms 25107389 VIN: 1GHFN5RS4KZ297988 Next Service: 121,000 kms **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips in windscreen

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

4wd

| <u>Interior Comments</u> | | | |
|--------------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Vasanthakumar Mayilswamy Inspected by:

| Create | u. 12 | z Dec z | .02-1 | | |
|------------------------------|----------------------------|---------|----------|--|--|
| | Pass | Fail | N/A | | |
| Engine | | | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | \(\times \) | | | | |
| Performance | ~ | | | | |
| Noise | ~ | | | | |
| Cooling System | | • | | | |
| Coolant condition | ~ | | | | |
| Performance | V | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | | | |
| Operation | ~ | | | | |
| Noise | ~ | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | V | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread | depth | of tyre | 25) | | |
| Left front 4.0 mm | | | | | |
| Right front | 4.0 | | mm | | |
| Left rear | | | mm | | |
| Right rear | 5.0 6.0 | | mm | | |
| Spare | 0 | Yes | | | |
| Suspension | | 103 | | | |
| Suspension performance | | | | | |
| Steering performance | | | | | |
| Shock absorbers | | | | | |
| | • | | | | |
| Air Conditioning / Heater | | | | | |
| Operation 🗸 | | | | | |
| Electrical / Accessories | | | | | |
| Head lights | • | | | | |
| Tail lights | • | | | | |
| Indicators | | | | | |
| Dashboard warning lights | • | | | | |
| Wipers (front & rear) | V V V V V V | | | | |
| Window winder FL | ' | | | | |
| Window winder FR | - | | | | |
| Window winder RL | ~ | | | | |
| Window winder RR | ~ | | | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | | | ' | | |
| Number of keys | 2 | | | | |
| Central locking | ~ | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | ~ | | | | |
| Reversing camera | ~ | | | | |
| Data: 10 Dac 20 | | | | | |

10 Dec 2024

Signature:

| I have read and understood this condition guide. Name: | |
|--|--|
|--|--|