

Report ID: 25,107,499 Version: 1 Created: 04 Dec 2024

Make:	Nissan	Model:	Elgrand	Body Style:	Wagon		Pass	Fail	N/A
Year:	2010	Registration:	KZU288	<b>Reg Expiry:</b>	01 Jun 2025	Engine	1	I	
WoF Expiry:	27 Mar 2025	Odometer:	182,387 Kms	Good No:	25107499	Oil level	~		
VIN:	7AT0DH6MX17004142	Next Service:	238,000 kms	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
					S	Performance	V		
Key:	S	-0	s s			Radiator / Hoses (visual)	V		
S = scratch D = dent						Transmission			
D = dent R = rust	sc			715	HILLS	Operation	~		
PT = paint defe				$\left( \left  \left( \right) \right\rangle \right)$		Noise	r		
C = crack					R	Clutch			~
P = pin dent	HID			$\langle \rangle$	74116	CV joints	~		
* = decals	sc 916			Ta		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W D S D W S						Performance	~		
Body Incr	pection Commonts	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Stone chips in windscreen						Tyres (lowest observed tread depth of tyres)			es)
Tyre mobility kit available									mm
						Right front		7	mm
						Left rear		7	mm
Conditions During Body Inspection: Dry						Right rear			mm
						Spare N/A			
Under Carriage & Under Bonnet Inspection Comments					Suspension	1			
2wd					Suspension performance	~			
Engine oil leak						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater		1	
						Operation	~		
Interior Comments						Electrical / Accessories	•		•
Seats	Average					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		•
Road Conditions During Test Drive: Dry						Central locking	~		
, ,						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
·	Increasted hun Vacanthalumar Maviluuramu								
Inspected by: Vasanthakumar Mayilswamy Date: 04 Dec 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....