

Report ID: 25,107,826 1 Version: 30 Dec 2024 Created:

Make:	Suzuki	Model:	Vitara	Body Style:	SUV		Pass	Fail	N/A	
Year:	2021	Registration:	NSS297	Reg Expiry:	21 Mar 2025	Engine		i	1	
WoF Expiry:	07 Aug 2025	Odometer:	60,086 Kms	Good No:	25107826	Oil level	~			
VIN:	TSMLYDA1S00A1137(Next Service:	66,000 kms	Service Histor	y: Yes	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~			
			S S			Performance	~			
Key:		-0				Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission				
B = rust	s dia			210	HIV	Operation	~			
PT = paint defe	ect NP				70111	Noise	~			
C = crack						Clutch			~	
P = pin dent	sc dR				74116	CV joints	~			
* = decals				10		Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
vv – signinican			S		D	Performance	~			
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~			
body inspection comments						Tyres (lowest observed tread depth of tyres)				
Stone chips in windscreen						Left front 3 mm			mm	
						Right front	4	1	mm	
						Left rear	3	3	mm	
Conditions During Body Inspection: Dry						Right rear	3 mm			
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Fwd						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Comoto						Tail lights	~			
Carpets	Good					Indicators	~			
Panels	Good					Dashboard warning lights	~			
Dashta	rd					Wipers (front & rear)	~			
Dashboa	rd Good					Window winder FL	~			
	-					Window winder FR	~			
<u>General Comments</u>						Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	<			
						Radio (basic test only)	~			
						CD (basic test only)			~	
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~			
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspected	Inspected by: Vasanthakumar Mayilswamy Date: 30 Dec 2024									

I have read and understood this condition guide.

Name:

Signature: