

Report ID: 25,506,789 Version: 2 18 Nov 2024 Created:

Make:	Nissan	Model:	Leaf	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2018	Registration:	QGJ991	Reg Expiry:	27 Dec 2024	Engine			
WoF Expiry:	20 Nov 2024	Odometer:	45,769 Kms	Good No:	25506789	Oil level			~
VIN:	7AT0DH8KX23009356	Next Service:	0	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for any and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition		~	
						Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			L
D = dent	- HE			ZIS		Operation	~		
R = rust PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~		
C = crack				+		Clutch			~
P = pin dent					거네	CV joints	~		-
* = decals	- 616			- No	HIP	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S						Performance	~		
Darah L		Note: som	ne defects & blemishe	s may not be disc	blayed in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	-	oftvre	Ls)
					Left front 6 mm				
						Right front		5	 mm
						Left rear		-	mm
						Right rear			
Conditions During Body Inspection: Dry									mm
Under Carriage & Under Bonnet Inspection Comments						Spare N/A Suspension			
Fwd						Suspension performance	~		
1 114						Steering performance	~		
						Shock absorbers			
							~		
						Air Conditioning / Heater			
Interior Comments						Operation			
Good						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		<u> </u>
Panels						Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		$\left \right $
						Window winder FL	~		$\left \right $
Concerto						Window winder FR	~		ļ
General Comments Note: parcel tray missing,						Window winder RL	~		<u> </u>
	r day missing,					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
с		11.1				Remote locking	~		
Engine Timing Mechanism: Unknown						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Marlon Espena Date: 18 Nov 2024									

I have read and understood this condition guide.

Name:

Signature: