

Report ID: 25,529,281 Version: 1 27 Feb 2024 Created:

Make:	Subaru	Model:	Impreza	Body Style:	Wagon		Pass	Fail	N/A
Year:	2013	Registration:	r	Reg Expiry:		Engine			L
WoF Expiry:		Odometer:	124,805 Kms	Good No:	25529281	Oil level	~		
VIN:	7AT0GF09X24003858	Next Service:		Service Histor		Smoke & fumes	~		
					,	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
						Operation 🖌			
R = rust	mp			10		Noise			
PT = paint def C = crack	ect			+		Clutch	~		
P = pin dent	Ho								~
* = decals	dig					CV joints	~		
SC = stone chi	ps US			10		Wheel bearings	~		
W = significant scuffs						Brakes			
						Performance	~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
					Tyres (lowest observed tread depth of tyres)				
						Left front	6.	.5	mm
						Right front	6.	.5	mm
						Left rear	6	5	mm
Conditions During Body Inspection: Dry						Right rear	6 mm		
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
St						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Compate	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry							~		
Remote locking							~		
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms: Reversit						Reversing camera	~		
Inspected by: Blair Robertson Date: 27 Feb 2024									

I have read and understood this condition guide.

Name:

Signature: