

Basic Vehicle Condition Guide

Report ID: 25,530,021

Version: 1


Created: 08 Mar 2024

Make: Model: Subaru ΧV **Body Style:** Hatchback

Year: 2017 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 23 Feb 2025 81,653 Kms 25530021 VIN: 7AT0GF1XX24057858 Next Service: 91200 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

28 Feb 2024 Inspected by: Greg Morgan

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	\(\times \)			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	V			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	depth	of tyre	es)	
Left front	5.0		mm	
Right front	4.0		mm	
Left rear	4.0		mm	
Right rear	4.0		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	~			
Window winder FL	~			
Window winder FR	V V V V V			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)			~	
Number of keys	2			
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	
Reversing camera	~			

I have read and understood this condition guide.

Name:

Signature: