

Report ID: 25,530,218 3 Version: 12 Dec 2024 Created:

Make:	Subaru	Model:	XV	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2018	<b>Registration:</b>	QWE952	Reg Expiry:		Engine	1	<u> </u>	1
WoF Expiry:		Odometer:	72,860 Kms	Good No:	25530218	Oil level	~		
VIN:	7AT0GF1XX24078020	Next Service:	82852	Service Histor	<b>y:</b> No	Smoke & fumes	~		<u> </u>
						Performance	~		<u> </u>
	port is not a warranty	oration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
	S		SC P		PW	Performance	~		
Key:	B	-0	SC P	-01-	PW	Radiator / Hoses (visual)	~		<u> </u>
S = scratch						Transmission			L
D = dent R = rust	w 6/5			715	HIL	Operation	~		
PT = paint defe				$\left( \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HIG				74114	CV joints	~		
* = decals	- Alt					Wheel bearings	~		
SC = stone chips						Brakes			L
W = significan	t scuffs	$\neg \varnothing$	SP		Р	Performance	~		
Padulaa	action Commonts	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			1 2s)
Fitted with snow tires all around									mm
						Right front	7.	.0	mm
						Left rear	7.	.0	mm
Conditions During Body Inspection: Dry						Right rear	7.0 mm		
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	· ·					Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		1
Road Conditions During Test Drive: Dry Central locking									
						Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only									~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
						• • • • •			
Inspected by: Sione Mae Date: 01 Mar 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....