

Report ID: 25,604,692 Version: 1 03 Apr 2024 Created:

| Make: | Subaru | Model: | Outback | Body Style: | Wagon | | Pass | Fail | N/A |
|--|--------------------------|----------------------|------------------------|--|-----------------------|--|------|------|-----|
| Year: | 2016 | Registration: | | Reg Expiry: | | Engine | 1 | | |
| WoF Expiry: | 02 Apr 2025 | Odometer: | 41,721 Kms | Good No: | 25604692 | Oil level | ~ | | |
| VIN: | 7AT0GF16X24026306 | Next Service: | 51721 | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | aration is made | for age and mileage | Parts have not | been dismantled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and th | his can be arranged fo | or an additional o | charge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | | -0 | | | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent R = rust | | | | 715 | SD SD | Operation | ~ | | |
| PT = paint defe | | F I | | $\left(\left \left(\right) \right\rangle \right)$ | | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | HID | | | | 74114 | CV joints | ~ | | |
| * = decals | - Alf | | | -No- | | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| vv = significant | | | | | | Performance | ~ | | |
| Body Incr | portion Commonts | Note: som | ne defects & blemishes | may not be disp | played in the diagram | Hand Brake | ~ | | |
| Body Inspection Comments | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | Left front | eft front 7 | | | |
| | | | | | | Right front | 7 | 7 | mm |
| | | | | | | Left rear | 7 | 7 | mm |
| Conditions During Body Inspection: | | | | | | Right rear | 7 mm | | mm |
| | | | | | | Spare | N/A | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | 1 | | 1 |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| | Good | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| | , Good | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | | | ~ |
| | | | | | | Number of keys | 2 | | |
| Road Conditions During Test Drive: Dry | | | | | | | ~ | | |
| | | | · | | | Remote locking | ~ | | |
| Engine Tir | ming Mechanism: | Timing (| Chain | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | ~ | | |
| | | | | | | | | | |
| Inspected by: Neil Honeyman Date: 03 Apr 2024 | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: