

Basic Vehicle Condition Guide

Reg Expiry:

Report ID: 25,672,093

Version: 2

Created: 13 Aug 2024

Make: Model: Mercedes-Benz A180 **Body Style:** Hatchback


Year: 2013 Registration:

WoF Expiry: **Odometer: Good No:** 30 May 2025 46,660 Kms 25672093 WDD1760422J058685 **Next Service:** 56,600 Kms Service History:

Note: This report is not a warranty

VIN:

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | |
|--------------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Lewis Dolamore 05 Jun 2024 Inspected by: Date:

Name:

| | Pass | Fail | N/A | |
|----------------------------------------------|-----------------------------------------|------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | <i>y y</i> | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | • | | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | > | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | > | | | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | 6.0 | | mm | |
| Right front | 6.0 | | mm | |
| Left rear | 4.0 | | mm | |
| Right rear | 4.0 | | mm | |
| Spare | | No | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | V V | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | 1 | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | VVV | | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | \(\times \) | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | • | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 1 | | | |
| Central locking | ' | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | | | | |

Signature: