

Report ID: 25,713,107 Version: 1 12 Jun 2024 Created:

Make: Model:		Body Style:		Pass	Fail N	I/A
Year: Registratio	n:	Reg Expiry:	Engine			
WoF Expiry: 10 Jun 2025 Odometer:	107,759 Kms	Good No: 25713107	Oil level	~		
VIN: 7AT0DH12X24101987 Next Servic	e: 117,000	Service History: No	Smoke & fumes	~		
		·	Performance	·		
Note: This report is not a warranty			Noise	~		
This report is a guide only. Consideration is ma diagnostic testing undertaken. The vehicle has b	een driven up to 50km	/h from cold. The Vendor recommends	Cooling System	·		
a full mechanical inspection prior to purchase an	d this can be arranged	for an additional charge.	Coolant condition	~		
			Performance	~		
Key:			Radiator / Hoses (visual)	~		
S = scratch			Transmission	•		
D = dent			Operation	~		
R = rust PT = paint defect		TIOHH	Noise	~		
C = crack	()) -		Clutch	•		
P = pin dent			CV joints			
* = decals			Wheel bearings	~		
SC = stone chips			Brakes	•		
W = significant scuffs			Performance	~	1	
	some defects & blamich	es may not be displayed in the diagram	Hand Brake	~		
Body Inspection Comments		les may not be displayed in the diagram	Tyres (lowest observed tread	•	of turos)	
			Left front			
				5		
			Right front	4		
			Left rear	6		
Conditions During Body Inspection:			Right rear	5 mm		
Under Carriage & Under Bonnet Inspection Comments		Spare	N/A			
onder carnage & onder bonnet inspec			Suspension			
			Suspension performance	~		
			Steering performance	~		
			Shock absorbers	~		
			Air Conditioning / Heater			
Interior Comments			Operation	~		
Good			Electrical / Accessories			
Seats			Head lights	~		
Carpets Good			Tail lights	~		
			Indicators	~		
Panels Good			Dashboard warning lights	~		
Dashboard Good			Wipers (front & rear)	~		
			Window winder FL	~		
			Window winder FR	~		
<u>General Comments</u>			Window winder RL	~		
			Window winder RR	~		
			Rear view mirrors	~		
			Radio (basic test only)	~		
			CD (basic test only)	~		
			Number of keys	1		
Road Conditions During Test Drive:	Dry		Central locking	~		_
-	•		Remote locking	~		
	g Chain		Sat. Nav. (basic test only)		v	/
Evidence of Cam Belt Replacement:	Not Applicable	Kms:	Reversing camera	~		
					•	_
Inspected by: Lewis Dolamore			Date: 12 Jun 202	24		

I have read and understood this condition guide.

Name:

Signature: