

Basic Vehicle Condition Guide

Report ID: 25,713,343


Version: 1

Created: 07 Jun 2024

Make: Model: Subaru Exiga **Body Style:** Wagon Year: 2015 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 04 Jun 2025 132,141 Kms 25713343 VIN: 7AT0GF1RX24019557 Next Service: 142,200 Kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Drivers seat poor		
Carpets	Good		
Panels	Cosmetic blemish on front right door card		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Hoani Saunders

Create	u. •	7 3411 2	021	
	Pass	Fail	N/A	
Engine	•	•		
Oil level	~			
Smoke & fumes	~			
Performance	> >			
Noise	~			
Cooling System		•		
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	depth	of tyre	es)	
Left front	7	.0	mm	
Right front	nt front 7.1		mm	
Left rear	7.0		mm	
Right rear	7	.2	mm	
Spare		Yes		
Suspension	•			
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	\(\times \)			
Dashboard warning lights	~			
Wipers (front & rear)	~			
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR	>			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	2			
Central locking	~			
Pamata lacking	.,			

I have read and understood this condition guide.

Name:

Signature:

06 Jun 2024

Remote locking

Reversing camera

Sat. Nav. (basic test only)

Date: