

## **Basic Vehicle Condition Guide**

Report ID: 25,720,767


Version: 2

Created: 11 May 2024

Make: Model: Honda Civic **Body Style:** Sedan Year: 2005 Registration: JNM482 Reg Expiry: 05 Jul 2024 WoF Expiry: **Odometer: Good No:** 17 Apr 2025 109,842 Kms 25720767 VIN: 7AT08G0WX14402648 Next Service: 119000 Service History: No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Note: some defects & blemishes may not be displayed in the diagram

Both front fog lights cracked,RR tail light broken ,LF door mirror casing base needs paint ,

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>					
Seats	wear,minor stains ,				
Carpets	wear,minor stains ,				
Panels	some of the interior door trim cloth coming off ,				
Dashboard	Average				

## **General Comments**

Drives okay, recent wof and service

Road Conditions During Test Drive: Dry

I have read and understood this condition guide.

**Engine Timing Mechanism:** Cambelt

**Evidence of Cam Belt Replacement:** 

Kms:

Name: .....

The state of the s		140		Reversing camera			
Inspected by:	Donovan Matara			Date:	29 Apr 202	24	
						Τ	

1		Pass	Fail	N/A				
	Engine							
	Oil level	~						
	Smoke & fumes	~						
	Performance	<b>V</b>						
	Noise	~						
	Cooling System			1				
	Coolant condition	~						
	Performance	~						
	Radiator / Hoses (visual)	~						
	Transmission							
	Operation	~						
	Noise	~						
	Clutch			~				
	CV joints	~						
	Wheel bearings	~						
	Brakes		ı					
	Performance	~						
	Hand Brake	~						
	Tyres (lowest observed tread	l depth	of tyre	es)				
	Left front	3	.4	mm				
	Right front	2	.8	mm				
	Left rear	2	.8	mm				
	Right rear	3.3		mm				
 	Spare		Yes					
	Suspension							
	Suspension performance	>						
	Steering performance	>						
	Shock absorbers	~						
	Air Conditioning / Heater							
l	Operation	~						
	Electrical / Accessories							
	Head lights	~						
	Tail lights	~						
	Indicators	~						
	Dashboard warning lights	<b>'</b>						
	Wipers (front & rear)	~						
	Window winder FL	~						
	Window winder FR	~						
	Window winder RL	V V V V V V						
	Window winder RR	~						
	Rear view mirrors							
	Radio (basic test only)	~						
	CD (basic test only)			<b>'</b>				
	Number of keys	1		1				
	Central locking	~						
l	Remote locking	~						
	Sat. Nav. (basic test only)			<b>'</b>				
	Reversing camera							
	Date: 29 Apr 202							

Signature: .....