

Basic Vehicle Condition Guide

Report ID: 25,741,507


Version: 2

Created: 14 May 2024

Make: Model: Subaru Outback **Body Style:** SUV Year: 2015 Registration: JDE689 Reg Expiry: 30 Jun 2024 WoF Expiry: **Odometer: Good No:** 25 May 2025 105,036 Kms 25741507 VIN: JF2BS9KC2FG007663 Next Service: 115000 Service History: No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Boo	av inspection	ľ
-----------------------	---------------	---

Under Carriage & Under Bonnet Inspection Comments

Interior Comments	5
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Lukin Koveskali Inspected by:

Engine Oil level Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake	Pass V V V V V V V V V	Fail	N/A
Oil level Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	V		
Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	V		
Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	V		· · ·
Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	V		· · ·
Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	V		V
Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance			v
Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance			
Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	V V V V		V
Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	V V V		V
Operation Noise Clutch CV joints Wheel bearings Brakes Performance	V V V		<i>'</i>
Noise Clutch CV joints Wheel bearings Brakes Performance	\(\times \)		·
Clutch CV joints Wheel bearings Brakes Performance	<i>y y y y</i>		V
CV joints Wheel bearings Brakes Performance	<i>y</i>		~
Wheel bearings Brakes Performance	V		
Brakes Performance	~		1
Brakes Performance			
			1
Hand Brake	~		
aiia bialle	~		
Tyres (lowest observed tread	l depth	of tyre	1 es)
Left front		.0	mm
Right front	5	.0	mm
Left rear		7	mm
Right rear		 7	mm
Spare		Yes	
Suspension	<u> </u>		
Suspension performance	~		
Steering performance	V		
Shock absorbers	~		
Air Conditioning / Heater			-
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	> > > >		
Window winder FL	~		
Window winder FR	~		
Window winder RL	ン ン ン		
Window winder RR	~		
Rear view mirrors	'		
Radio (basic test only)	~		
CD (basic test only)	•		~
Number of keys	2		
Central locking			
Remote locking	~		
Sat. Nav. (basic test only)			_
Reversing camera	~		-
· · · · · · · · · · · · · · · · · · ·	-		

Date: 08 May 2024

I have read and understood this condition guide. Name: Signature: