

Report ID: 25,741,553 Version: 3 02 Aug 2024 Created:

Make:	KIA	Model:	Sportage	Body Style:	SUV		Pass	Fail	N/A
Year:	2013	Registration:		Reg Expiry:	17 Sep 2024	Engine	1		1
WoF Expiry:	28 Dec 2024	Odometer:	157,469 Kms	Good No:	25741553	Oil level	~		
VIN:	KNAPC813SD7398852	Next Service:	162,000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	SW	-0	DW PW	-161-	SDW	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	sw 6/6			10-	SDW	Operation	~		
R = rust PT = paint defe				r In		Noise	~		
C = crack				+	РТ	Clutch			~
P = pin dent						CV joints	~		•
* = decals	SPSC 916				ETTPS-	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs P S W						Performance	~		
		Note: som	e defects & blemishes	may not be disr	blayed in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram								oftyre	() ()
Right rear bumper impact damage .						Tyres (lowest observed tread depth of tyres) Left front 4.0 mm			
						Right front			mm
						Left rear	5.		mm
									mm
Conditions During Body Inspection: Dry						Right rear	4.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
and canage a onder pomeenspection comments									
4WD						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
						Electrical / Accessories			
Seats	riveluge					Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
Concerto	ommorte					Window winder FR	~		
	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Central							~		
Engine Timing Mechanism. Timing Chain						Remote locking	~		
Engine Timing Mechanism: Timing Chain									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Marlon Espena Date: 07 Jun 2024									
Inspected by. Marion Espena Date: 07 Juli 2024									

I have read and understood this condition guide.

Name:

Signature: