

Basic Vehicle Condition Guide

Report ID: 25,742,174


Version: 3

Created: 28 Jun 2024

Make: Model: Mazda Mazda6 **Body Style:** Sedan Year: 2008 Registration: EQS130 Reg Expiry: 15 Jun 2024 WoF Expiry: **Odometer: Good No:** 19 Jan 2025 184,430 Kms 25742174 VIN: JM0GH105100116605 Next Service: 194,000 Kms **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Engine knocking, poor performance

| Interior Comments | | | |
|-------------------|----------------------|--|--|
| Seats | Drivers seat average | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

| | _ |
|---------|----------|
| General | Comments |

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Hoani Saunders Inspected by:

Name:

| | Pass | Fail | N/A |
|------------------------------|----------------------------|---------|--------|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | ~ | | |
| Performance | ~ | | |
| Noise | | ~ | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | V | | |
| Transmission | | | - |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | v | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | l depth | of tyre | 25) |
| Left front | | | mm |
| Right front | 4.2 | | mm |
| Left rear | 6.0 5.7 | | mm |
| Right rear | | | mm |
| Spare | 5.7 | | 111111 |
| Suspension | | Yes | |
| Suspension performance | ., | | |
| Steering performance | V | | |
| Shock absorbers | • | | |
| | V | | |
| Air Conditioning / Heater | _ | | |
| Operation | • | | |
| Electrical / Accessories | | | |
| Head lights | <i>V</i> | | |
| Tail lights | V V V V V V | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 2 | ı | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | ~ |
| Date: 07 May 20 | 24 | | |

Signature: