


<b>Make:</b> Mitsubishi	<b>Model:</b> Triton	<b>Body Style:</b> Utility
<b>Year:</b> 2015	<b>Registration:</b> JGK995	<b>Reg Expiry:</b> 20 Aug 2024
<b>WoF Expiry:</b> 19 Dec 2024	<b>Odometer:</b> 148,503 Kms	<b>Good No:</b> 25762605
<b>VIN:</b> MMAJYKL10GH00504	<b>Next Service:</b> 0	<b>Service History:</b> No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**  
S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs



**Body Inspection Comments** Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**  
4WD  
Left front tyre has a cut on the side wall .

**Interior Comments**

Seats	front passenger seat worn
Carpets	Average
Panels	Good
Dashboard	Good

**General Comments**  
Right number plate light not working  
Oil and filter service ., drivers seat missing knob.  
Left front check strap faulty . Sunglasses holder broken.  
Fault codes ,airbag light on dashboard  
Ac9c , heater 37c

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain  
Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints			✓
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	5	mm	
Right front	5	mm	
Left rear	5	mm	
Right rear	4	mm	
Spare		Yes	
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights		✓	
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera	✓		

Inspected by: Allan Young Date: 20 May 2024

I have read and understood this condition guide. Name: ..... Signature: .....