

## **Basic Vehicle Condition Guide**

Report ID: 25,777,869

Pass

1

V

/

V

1

Tyres (lowest observed tread depth of tyres)

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

**Transmission** 

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

**Hand Brake** 

Left front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Right front

Coolant condition Performance

Radiator / Hoses (visual)

Created: 28 May 2024

Fail

N/A

1

mm

mm

mm

 $\mathsf{mm}$ 

7.0

8.0

6.0

6.0

1

/

/

1

1


1

Yes

Make: Mitsubishi Model: Pajero **Body Style:** SUV Year: 2001 Registration: FJU82 **Reg Expiry:** 11 Mar 2025 WoF Expiry: **Odometer:** 01 May 2025 218,884 Kms **Good No:** 25777869 VIN: 7AT0CJ08X10103893 **Next Service:** 206000 Service History:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Rear centre Head rest missing, Petrol Flap Dented, Front Radiator support panel surface rust,

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Oil seepage R/F CV Boot Aera.

Interior Comments			
Seats	Average		
Carpets	Average		
Panels	Poor		
Dashboard	Average		

General	Comments

Inspected by:

**Road Conditions During Test Drive:** Dry

**Engine Timing Mechanism:** Cambelt

**Evidence of Cam Belt Replacement:** 

Chris Buckley

I have read and understood this condition guide.

	Sat. Nav. (basic test only)	V		
Kms:	Reversing camera	V		
Date: 28 May 2024				
Name:	Signature:			