

Report ID: 25,788,053 Version: 2 08 Jun 2024 Created:

Make:	Hyundai	Model:	Tucson	Body Style:	SUV		Pass	Fail	N/A
Year:	2018	Registration:	LSZ228	Reg Expiry:	20 Nov 2024	Engine			L
WoF Expiry:	07 Jun 2025	Odometer:	63,730 Kms	Good No:	25788053	Oil level	~		
VIN:	KMHJ3814MKU85380	Next Service:	73,500 kms	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		6	Danta harra nat	harmaltan and an	Noise	· ·		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:	Г	-0		- A <sup>PT</sup>		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	- HE			TIS		Operation	~		
R = rust PT = paint defe				$\prod$		Noise	~		
C = crack						Clutch			~
P = pin dent	-110				74 <u>11</u>	CV joints	~		-
* = decals	- Alf			- Jul		Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs				N	Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
						Left front	7.	1	mm
						Right front	7.	1	mm
						Left rear	5.	7	mm
Conditions During Body Inspection: Dry						Right rear	4.2 mi		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking							~		
		<b></b>				Remote locking	~		
-	ming Mechanism:	Timing (		IZ .		Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Hoani Saunders Date: 05 Jun 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....