

Basic Vehicle Condition Guide

Report ID: 25,789,275

Version:

20 Jun 2024 Created:


Make: Model: Subaru Levorg **Body Style:** Year: 2015 Registration: Reg Expiry: WoF Expiry: 11 Jun 2025 **Odometer: Good No:** 64,291 Kms

25789275 Next Service: 74,289 km Service History:

Note: This report is not a warranty

VIN:

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection:	Dry
------------------------------------	-----

Under Carriage & Under Bonnet Inspection Comments

4WD.

Interior Comments	<u>5</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

	_
General	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

12 Jun 2024 Inspected by: Imraan Bryant

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	V		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes		ı	
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	9	.0	mm
Right front	9	.0	mm
Left rear	9	.0	mm
Right rear	9	.0	mm
Spare		No	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	V V V V V V V V V V V V V V V V V V V		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		

I have read and understood this condition guide.

Name:

Signature: