

Basic Vehicle Condition Guide

Report ID: 25,791,409

Version: 2

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Suspension performance Steering performance

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Operation

Head lights Tail lights Indicators

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 25 Jun 2024

Pass

~

~

/

V

1

Tyres (lowest observed tread depth of tyres)

Fail

N/A

1

mm

mm

mm

 mm

3.0

3.5

2.5

3.0

1

/


/

Yes

Make: Model: Ford **Focus Body Style:** Wagon Year: 2013 Registration: **GWF759 Reg Expiry:** 16 Sep 2024 WoF Expiry: **Odometer:** 29 Jun 2025 151,807 Kms Good No: 25791409 VIN: WF0LXXGCBLDJ58433 Next Service: 161,800kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stain and molding on trim and deck tray.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	Average			
Carpets	Average			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement:

	window winder RL	"		
	Window winder RR	~		
	Rear view mirrors	~		
	Radio (basic test only)	~		
	CD (basic test only)		~	
	Number of keys	2		-
	Central locking	~		
	Remote locking	~		
	Sat. Nav. (basic test only)			~
Kms:	Reversing camera			~
	Date: 17 Jun 20	24		
	 Signature:			

Evidence of Cam Belt Replacement: No	Kms:	Reversing camera	<u> </u>			
Inspected by: Yuki Itohara		Date: 17 Jun 202	24			
have read and understood this condition guide.	Name:	Signature:	Signature:			