

Report ID: 25,798,017 Version: 4 30 Oct 2024 Created:

Make:	Ford	Model:	Territory	Body Style:	SUV		Pass	Fail	N/A
Year:	2013	Registration:	GWA280	Reg Expiry:	29 Oct 2024	Engine			
WoF Expiry:	31 Jul 2025	Odometer:	272,589 Kms	Good No:	25798017	Oil level	~		
VIN:	6FPAAAJGATCT21104	Next Service:	279,700kms	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	SC		S P SC P SC		P SC	Performance	~		
Key:	La C	-0	SPSC PSC		PSC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust				715	HILS	Operation	~		
PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	ING HIR				74116	CV joints	~		
* = decals	PSC 916				ELD'S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs PT SC S D SC S SC S						Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Front bumper cracked & lower grille damaged.						Tyres (lowest observed tread	d depth	of tyre	2S)
Chipped windscreen.						Left front 6.0 n			mm
						Right front	7	.0	mm
						Left rear	8	.0	mm
Conditions During Body Inspection: Dry						Right rear	8.0 n		mm
Conditions Daming Dody inspection. Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories	1		L
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets	-					Indicators	~		
Panels	Headlining	g damaged at rea	ar.			Dashboard warning lights	~		
	. Steering w	heel worn.				Wipers (front & rear)	~		
Dashboa	rd					Window winder FL		~	
						Window winder FR		~	
	<u>Comments</u>					Window winder RL		~	
AWD diesel	auto SUV. s not working.					Window winder RR		~	
	s not not nig.					Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	Drive:	Dry			Central locking	~		
	-					Remote locking	~		
-	ming Mechanism:	Cambel	t			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	es	Kms: 27	1,850	Reversing camera			V
Inspected by: Daryll Timms Date: 22 Aug 2024									
Inspected by: Daryll Timms Date: 22 Aug 2024									

I have read and understood this condition guide.

Name:

Signature: