

Report ID: 25,800,582 Version: 2 24 Jun 2024 Created:

| Make:  | Ford                     | Model:               | Ranger               | Body Style:         | Utility              |   | Pass | Fail | N/A      |
|--|--------------------------|----------------------|----------------------|---------------------|----------------------|---|------|------|----------|
| Year:  | 2019                     | <b>Registration:</b> | MFE914               | <b>Reg Expiry:</b>  | 29 Jul 2024          | Engine                                      |      |      |          |
| WoF Expiry:  | 21 Jun 2025              | Odometer:            | 192,141 Kms          | Good No:            | 25800582             | Oil level                                   | ٢    |      |          |
| VIN:   | MPBUMFF50JX191233        | Next Service:        | 202000               | Service History     | <b>y:</b> No         | Smoke & fumes                               | ~    |      |          |
|  |                          |                      |                      |                     |                      | Performance                                 | ~    |      |          |
| Note: This report is not a warranty<br>This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or   |                          |                      |                      |                     |                      | Noise                                       | ~    |      |          |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. |                          |                      |                      |                     |                      | Cooling System                              |      |      |          |
| a full mechan  | ical inspection prior to | purchase and t       | his can be arranged  | for an additional c | harge.               | Coolant condition                           | ~    |      |          |
|  |                          |                      |                      |                     |                      | Performance                                 | ~    |      |          |
| Key:   |                          | -0                   |                      | 50-                 |                      | Radiator / Hoses (visual)                   | ~    |      |          |
| S = scratch  | ALE                      | Transmission         |                      |                     |                      |   |      |      |          |
| D = dent<br>R = rust   | s dia                    |                      |                      | 210                 | HILLS                | Operation                                   | ~    |      |          |
| PT = paint defe  |                          | r I                  |                      |                     |                      | Noise                                       | ~    |      |          |
| C = crack  |                          |                      |                      | $+ \mathbf{\nabla}$ |                      | Clutch                                      |      |      | ~        |
| P = pin dent   | HIG                      |                      |                      | $\rightarrow$       | 74116                | CV joints                                   | ~    |      |          |
| * = decals   | sc 916                   |                      |                      | TO                  | AID -                | Wheel bearings                              | ~    |      |          |
| SC = stone chips   |                          |                      |                      |                     |                      | Brakes                                      |      |      |          |
| W = significant scuffs   |                          |                      |                      |                     |                      | Performance                                 | ~    |      |          |
| Darla  |                          | Note: son            | ne defects & blemish | les may not be disp | layed in the diagram | Hand Brake                                  | ~    |      |          |
| body inspection comments   |                          |                      |                      |                     |                      | Tyres (lowest observed tread depth of tyres |      |      | L<br>es) |
| Windscreen stone chip  |                          |                      |                      |                     |                      | Left front 3.0 mm                           |      |      |          |
|  |                          |                      |                      |                     |                      | Right front                                 | 3.   | -    | <br>mm   |
|  |                          |                      |                      |                     |                      | Left rear                                   | 1    | -    | mm       |
| Canalitian   | - Dunin - De du la s     |                      |                      |                     |                      | Right rear                                  |      | -    | mm       |
| Conditions During Body Inspection:   |                          |                      |                      |                     |                      | Right rear 10 mm<br>Spare Yes               |      |      |          |
| Under Carriage & Under Bonnet Inspection Comments  |                          |                      |                      |                     |                      | Suspension                                  |      |      |          |
|  |                          |                      |                      |                     |                      | Suspension performance                      | ~    |      | I        |
|  |                          |                      |                      |                     |                      | Steering performance                        | ~    |      |          |
|  |                          |                      |                      |                     |                      | Shock absorbers                             | ~    |      |          |
|  |                          |                      |                      |                     |                      | Air Conditioning / Heater                   | V    |      |          |
|  |                          |                      |                      |                     |                      | ]   |      |      |          |
| Interior Comments  |                          |                      |                      |                     |                      | Operation                                   |      |      |          |
| Average  |                          |                      |                      |                     |                      | Electrical / Accessories                    |      |      |          |
| Seats  | 5                        |                      |                      |                     |                      | Head lights                                 | ~    |      |          |
| Carpets  | Average                  |                      |                      |                     |                      | Tail lights                                 | ~    |      |          |
|  | Average                  |                      |                      |                     |                      | Indicators                                  | ~    |      |          |
| Panels   | Average                  |                      |                      |                     |                      | Dashboard warning lights                    | ~    |      | -        |
| Dashboa  | rd Average               |                      |                      |                     |                      | Wipers (front & rear)                       | ~    |      |          |
|  |                          |                      |                      |                     |                      | Window winder FL                            | ~    |      |          |
| General  | Comments                 |                      |                      |                     |                      | Window winder FR                            | ~    |      |          |
|  |                          |                      |                      |                     |                      | Window winder RL                            | ~    |      |          |
|  |                          |                      |                      |                     |                      | Window winder RR                            | ~    |      |          |
|  |                          |                      |                      |                     |                      | Rear view mirrors                           | ~    |      |          |
|  |                          |                      |                      |                     |                      | Radio (basic test only)                     | ~    |      |          |
|  |                          |                      |                      |                     |                      | CD (basic test only)                        |      |      | ~        |
|  |                          |                      |                      |                     |                      | Number of keys                              | 1    |      |          |
| Road Con   | ditions During Tes       | t Drive:             | Dry                  |                     |                      | Central locking                             | ~    |      |          |
| Engine   | ning Machaniana          | Timeline             | Chain                |                     |                      | Remote locking                              | ~    |      |          |
| Engine Timing Mechanism: Timing Chain  |                          |                      |                      |                     |                      | Sat. Nav. (basic test only)                 |      |      | ~        |
| Evidence   | of Cam Belt Replac       | ement: N             | lot Applicable       | Kms:                |                      | Reversing camera                            | ~    |      |          |
| Inspected  | d by: Lukin Koveskali    |                      |                      |                     |                      | Date: 10 Jun 20                             | 24   |      |          |
| L  | •                        |                      |                      |                     |                      |   |      |      |          |

I have read and understood this condition guide.

Name: .....

Signature: .....