

<b>Make:</b> Subaru	<b>Model:</b> Impreza	<b>Body Style:</b> Hatchback
<b>Year:</b> 2013	<b>Registration:</b> QML746	<b>Reg Expiry:</b> 13 Jul 2024
<b>WoF Expiry:</b>	<b>Odometer:</b> 155,598 Kms	<b>Good No:</b> 25802586
<b>VIN:</b> 7AT0GF09X22019656	<b>Next Service:</b> 165000	<b>Service History:</b> No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**  
 S = scratch  
 D = dent  
 R = rust  
 PT = paint defect  
 C = crack  
 P = pin dent  
 \* = decals  
 SC = stone chips  
 W = significant scuffs

**Body Inspection Comments**  
 Note: some defects & blemishes may not be displayed in the diagram  
 Poor paint repair to rear bumper and drivers door

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**  
 . Poor paint repair to rear bumper and drivers door

**Interior Comments**

Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

**General Comments**  
 A/c working during inspection. Radio unit in Japanese. Radio has Bluetooth but is an older type may not work on all phones. No parcel tray assembly. Inflation device in boot but no tyre sealant. 2wd model

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain  
 Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Reuben Harvey Date: 07 Jun 2024

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	3.5	mm	
Right front	3.5	mm	
Left rear	3.5	mm	
Right rear	3.5	mm	
Spare	N/A		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera			✓

I have read and understood this condition guide. Name: ..... Signature: .....