

Report ID: 25,804,117 Version: 1 03 Jul 2024 Created:

Make:	Ford	Model:	Ranger	Body Style:	Utility		Pass	Fail	N/A
Year:	2013	Registration:	QQC903	Reg Expiry:	01 Oct 2024	Engine			
WoF Expiry:	25 Jun 2025	Odometer:	129,357 Kms	Good No:	25804117	Oil level	~		
VIN:	MNAUMFF50DW1890	Next Service:	139000	Service Histor	y: No	Smoke & fumes	~		
	_					Performance	~		
	port is not a warranty a quide only Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	SC		P SC P SC		SC	Performance	~		
Key:	Lise (-0	PSC PSC	-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SSC						Operation	~		
PT = paint defe		F		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
* = decals SC 919 SD						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC SC SC S						Performance	~		
Podylog	action Commonts	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Nudge bar front bumper,snorkel fitted to the RF guard,						Tyres (lowest observed tread depth of tyres)			es)
Nuuge bai nont bumper,snorkei niteu to the kr guaru,						Left front	11	.2	mm
						Right front	11	.3	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry						Right rear	10.0 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater		1	
L						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	worn,					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
<u></u>	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	·					Window winder FR	~		
General Comments						Window winder RL	~		
Drives okay	',					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
	-		•			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
								1	
Inspected by: Donovan Matara Date: 12 Jun 2024									

I have read and understood this condition guide.

Name:

Signature: