

Report ID: 25,807,505 Version: 2 11 Jun 2024 Created:

Make:	BMW	Model:	X5	Body Style:	Wagon		Pass	Fail	N/A
Year:	2011	<b>Registration:</b>	HTW309	<b>Reg Expiry:</b>	10 Feb 2024	Engine			
WoF Expiry:	17 Jul 2024	Odometer:	160,055 Kms	Good No:	25807505	Oil level	~		
VIN:	WBAZW42000L46470.	Next Service:	163,901 km	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
	W				W	Performance	~		
Key:		-0			V	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
B = rust						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
* = decals						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W W						Performance	~		
Bodylac		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			es)
L/F wing mirror damaged&wont retract.						Left front 6 m			mm
						Right front	e	5	mm
						Left rear		7	mm
Conditions During Body Inspection: Wet						Right rear			mm
						Spare No			
Under Carriage & Under Bonnet Inspection Comments					Suspension				
4WD.						Suspension performance	~		
Oil leak und	lerside.					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
r						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Poor					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	1				I	Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
Service due soon. AC COLD 7c HOT 50c.						Window winder RR	~		
AC COLD /	. HOT SUC.					Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Imraan Bryant Date: 11 Jun 2024									

Name: .....