

Basic Vehicle Condition Guide

Report ID: 25,808,220


Version: 1

Created: 18 Jun 2024

Make: Model: Nissan Elgrand **Body Style:** Wagon Year: 2006 Registration: PGL508 **Reg Expiry:** 02 Aug 2024 WoF Expiry: **Odometer:** 13 Oct 2024 220,910 Kms **Good No:** 25808220 VIN: 7AT0DH6MX1715250: Next Service: no service history **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Rhf door has play. Front bumper poorly secured. Headlights faded

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Oil leaks. Rhf ball joint worn. Rhf tyre has edge wear. Battery positive terminal poorly secured. Battery failed test low cca.

Interior Comme	<u>ents</u>
Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

General Comments

Service prompt on screen. Rhr window doesn't operate. Vehicle required jump start. Lhs camera blurry. Curtain assembly broken. Drivers door cracks when opened. Lh middle seat missing patch of fabric

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

11 Jun 2024 Inspected by: Reuben Harvey Date:

Name:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	~			
Performance	<i>V V</i>			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission		!		
Operation	~			
Noise	~			
Clutch			~	
CV joints			~	
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front	5	.0	mm	
Right front	5	.0	mm	
Left rear	4.5		mm	
Right rear	4.5		mm	
Spare		Yes		
Suspension		ı		
Suspension performance		~		
Steering performance	~			
Shock absorbers	•			
Air Conditioning / Heater				
Operation	-			
Electrical / Accessories				
Head lights	-			
Tail lights	•			
Indicators	VVV			
Dashboard warning lights	<i>V</i>			
Wipers (front & rear) Window winder FL				
Window winder FR	V			
Window winder RL	<i>v</i>			
Window winder RR		./		
Rear view mirrors	V			
Radio (basic test only)	<i>y</i>			
CD (basic test only)	~			
Number of keys	1			
Central locking	· /			
Remote locking	·			
Sat. Nav. (basic test only)			~	
Reversing camera	_		<u> </u>	
		1	1	

Signature: