

Basic Vehicle Condition Guide

Report ID: 25,809,084


Version: 3

Created: 20 Jun 2024

Make: LDV Model: V80 **Body Style:** Van Year: 2014 Registration: HHJ437 Reg Expiry: 27 May 2025 WoF Expiry: **Odometer:** 04 Jun 2025 165,665 Kms **Good No:** 25809084 VIN: LSKG5GL13DA226802 Next Service: 171,800 Kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Equipped with platform tailgate lift. Master switch located side of drivers seat. Operating controls located LH side of van.

Radio antenna zip tied.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Minor engine oil leak.

| <u>Interior Comments</u> | | | |
|--------------------------|-------------------------------|--|--|
| Seats | Good | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average, steering wheel worn. | | |

General Comments

Reverse camera fail.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

12 Jun 2024 Inspected by: Troy Smith Date:

Name:

| Create | u. 20 | J Jun 2 | 024 | |
|--|--------------|---------|-----|--|
| | Pass | Fail | N/A | |
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | V | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | • | • | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | • | • | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | \(\times \) | | | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | 5.0 | | mm | |
| Right front | 5.0 | | mm | |
| Left rear | 8.5 | | mm | |
| Right rear | 6.0 | | mm | |
| Spare | | | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | ! | • | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | \(\times \) | | | |
| Window winder FL | ~ | | | |
| Window winder FR | ~ | | | |
| Window winder RL | | | ~ | |
| Window winder RR | | | ~ | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | | | ~ | |
| Number of keys | 2 | ı | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | | ~ | | |
| | | l | | |

Signature: