

Basic Vehicle Condition Guide

Report ID: 25,815,124


Version: 1

Created: 13 Jun 2024

Make: Model: Mazda Bt-50 **Body Style:** Utility Year: 2017 Registration: KLZ344 Reg Expiry: 01 Apr 2025 WoF Expiry: **Odometer:** 27 May 2025 209,689 Kms **Good No:** 25815124 VIN: MM0UR0YG10067449 Next Service: 210,982 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Headlamps cloudy Aftermarket deck/toolbox fitted RH/R of toolbox bent

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Coolant below "Min" mark

| Interior Comments | | | |
|-------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

General Comments

Seats badly stained Holes in dash Roof lining stained LH air vent broken

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: **Timing Chain**

Evidence of Cam Belt Replacement: Not Applicable Kms:

Andre Richardson 13 Jun 2024 Inspected by:

Name:

| | Pass | Fail | N/A |
|------------------------------|--|---------|-----|
| Engine | | , | |
| Oil level | ~ | | |
| Smoke & fumes | > > | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | | ~ | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | depth | of tyre | es) |
| Left front | 1 | 2 | mm |
| Right front | 12 | | mm |
| Left rear | 5 | | mm |
| Right rear | 5 | | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | \(\times \) \(\t | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | | | ~ |
| Window winder RR | | | ~ |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | ~ | | |
| | | | |

Signature: