

Report ID: 25,817,040 Version: 4 03 Jul 2024 Created:

Make:	Hyundai	Model:	Elantra	Body Style:	Sedan		Pass	Fail	N/A
Year:	2019	Registration:	MLF450	Reg Expiry:	30 Mar 2025	Engine			
WoF Expiry:	03 Jul 2025	Odometer:	106,577 Kms	Good No:	25817040	Oil level	~		
VIN:	KMHD841FMLU98509	Next Service:	116,000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	unting is mode	for one and miles as	Danta hava nat	hoon dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
		_				Performance	~		
Key:		-0	SW	-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
						Operation 🖌			
R = rust PT = paint defe				\prod	JHIA	Noise	~		
C = crack				+		Clutch	•		~
P = pin dent						CV joints	~		•
* = decals	- MIK			AL.	EIIR	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance			
		Note: som	e defects & blemisher	s may not be disr	laved in the diagram	Hand Brake			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							• • • • • •		
						Tyres (lowest observed tread depth of tyres)			
						Left front	7.		mm
						Right front	7.		mm
Left rear							7.		mm
Conditions During Body Inspection: Wet						Right rear	7.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
FWD						Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			
Seats	0000					Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
Concerto	ommonte					Window winder FR	~		
	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Wet									
		T !	î h a î n			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms: Beversing camera									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Marlon Espena Date: 03 Jul 2024									

I have read and understood this condition guide.

Name:

Signature: