

Basic Vehicle Condition Guide

Report ID: 25,822,254


Version: 1

26 Jun 2024 Created:

Make: Model: Mitsubishi Delica **Body Style:** Van Year: 2007 Registration: MLY69 Reg Expiry: 14 May 2025 **Odometer:** WoF Expiry: 18 Oct 2024 195,814 Kms **Good No:** 25822254 VIN: 7AT0CJ0PX19012464 **Next Service:** 203400 kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Minor windscreen chips.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Poor		
Carpets	Poor		
Panels	Poor		
Dashboard	Poor		

General Comments

Right number plate light out. Very dirty inside. Left electric door not working. Reverse Camera not clear. All 4 door handles badly faded.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: **Timing Chain**

Evidence of Cam Belt Replacement: Not Applicable Kms:

Chris McQuade 25 Jun 2024 Inspected by:

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	\(\times \)		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•	!	
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	5	.0	mm
Right front	5.0		mm
Left rear	7.0		mm
Right rear	5.3 mm		
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers		~	
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	\(\times \) \(\t		
Window winder FL	~		
Window winder FR			
Window winder RL	V		
Window winder RR	1		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1	1	1
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			\ <u>\</u>
i '			1 -
Reversing camera	~		

Signature: