

Basic Vehicle Condition Guide

Report ID: 25,837,693


Version: 2

Created: 11 Jul 2024

Make: Model: Ssangyong Korando **Body Style:** SUV Year: 2021 Registration: NPS692 Reg Expiry: 08 Jul 2024 **Odometer:** WoF Expiry: **Good No:** 06 Jul 2024 79,443 Kms 25837693 VIN: KPT70A1YSMP054879 **Next Service:** 90000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

No underbody inspection

Interior Comments		
Seats	Good	
Carpets	Good	
Panels	scratches, wear	
Dashboard	Good	

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Melissa Wilson Date: 11 Jul 2024 Inspected by:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	v		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes	_		
Performance	V		
Hand Brake	<i>'</i>		
Tyres (lowest observed treac	l depth	of tyre	25)
Left front		3	mm
Right front		.1	mm
Left rear		.1 .9	mm
Right rear		. <i>.</i> .7	mm
Spare	0	./ N/A	
Suspension		IN/A	
Suspension performance			
Steering performance			
Shock absorbers			
Air Conditioning / Heater	•		
Operation Electrical / Accessories	<i>V</i>		
Head lights	-		
Tail lights	•		
Indicators	•		
Dashboard warning lights	V V V V V		
Wipers (front & rear)	<i>V</i>		
Window winder FL	<i>\</i>		
Window winder FR	-		
Window winder RL	~		
Window winder RR	V		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			'
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		
Date: 11 Jul 202	1		

I have read and understood this condition guide.

Name	