

Basic Vehicle Condition Guide

Report ID: 25,838,649


Version: 3

Created: 11 Jul 2024

Make: Model: Mazda CX-9 **Body Style:** SUV Year: 2019 Registration: MAD883 Reg Expiry: 27 Aug 2024 **Odometer:** WoF Expiry: **Good No:** 07 Mar 2024 95,860 Kms 25838649 VIN: JM0TC4WLA00312376 Next Service: 64,300 km Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

L/F/L/R&R/R tyres have scalloping.

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

4WD.

| Interior Comments | | | |
|-------------------|------|--|--|
| Seats | Poor | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Service overdue. WOF EXPIRED.

Service due pops up on dash.

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

11 Jul 2024 Inspected by: Eleoit Kumar Date:

Name:

| | | 1 | | |
|---|---------------------------------------|------|----------|--|
| | Pass | Fail | N/A | |
| Engine | | ı | 1 | |
| Oil level | ~ | | | |
| Smoke & fumes | <i>v v</i> | | | |
| Performance | ~ | | | |
| Noise | ' | | | |
| Cooling System | | 1 | I | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | 1 | 1 | |
| Operation | V | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | ı | 1 | 1 | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | : | 3 | mm | |
| Right front | : | 3 | mm | |
| Left rear | | 1 | mm | |
| Right rear | 3 | | mm | |
| Spare | | Yes | | |
| Suspension | ı | ı | | |
| Suspension performance | ~ | | | |
| Steering performance | <i>V</i> | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | 1 | ı | | |
| Operation | ~ | | | |
| Electrical / Accessories | 1 | ı | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | | ~ | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | | | ' | |
| Number of keys | 1 | | 1 | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | ~ | | | |
| Reversing camera | ' | | | |
| | | | | |

Signature: