

Report ID: 25,842,411 3 Version: 12 Dec 2024 Created:

Make:	Subaru	Model:	Impreza	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2012	Registration:		Reg Expiry:		Engine	1	l	1
WoF Expiry:	09 Jul 2025	Odometer:	80,458 Kms	Good No:	25842411	Oil level	~		
VIN:	7AT0GF09X24009609	Next Service:	90,000kms	Service Histor	' y: Yes	Smoke & fumes	~		
						Performance	r		
	port is not a warranty		for and milago	Darte have not	t been dismonthed or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional	charge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	- HIE			ZIS		Operation	~		
R = rust PT = paint def	ect NIP			$\left(\left \right\rangle \right)$		Noise	~		
C = crack				+		Clutch			~
P = pin dent					74114	CV joints	~		
* = decals	- All			-No-		Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scutts					Performance	~		
Deduction		Note: son	ne defects & blemishes	may not be dis	played in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tyre	es)
						Left front	8		mm
						Right front	8		mm
						Left rear	8		mm
Conditions During Body Inspection:						Right rear			mm
Conditions During Body Inspection: Dry						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
All wheel d	rive.					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	ord Good					Window winder FL	~		
	I					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2	1	1
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		-
									1
Inspected by: Takaya Murayama Date: 10 Jul 2024									

I have read and understood this condition guide.

Name:

Signature: