

Report ID: 25,847,537 Version: 1 Created: 03 Jul 2024

Make:	Fiat	Model:	Punto	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2015	Registration:	JHR164	Reg Expiry:	15 Dec 2024	Engine			
WoF Expiry:	14 Dec 2024	Odometer:	74,611 Kms	Good No:	25847537	Oil level	~		
VIN:	ZFA19900000980623	Next Service:	0	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside		for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	lical inspection prior to	purchase and t	his can be arranged fo	or an additional o	narge.	Coolant condition	~		
	S D S		S D SC		SC	Performance	~		
Key:	130 []3	-0	3030	5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent	TE				An	Transmission	1		1
B = rust	s sc			710	HIVS	Operation	~		Τ
PT = paint def	ect NP				ארור	Noise	~		
C = crack						Clutch			~
P = pin dent	HE				74116	CV joints	~		1
* = decals	sc glk			-Jos		Wheel bearings	~		-
SC = stone chips						Brakes			
W = significant scuffs S SC S SC SC SC SC						Performance	Performance 🖌		
Podulaci	action Commonts	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		+
Body Inspection Comments Mirror casings need paint ,						Tyres (lowest observed tread	observed tread depth of tyres)		
WIITOT Cash	igs need paint ,					Left front	2	.6	mm
						Right front		.2	mm
						Left rear		.6	mm
Conditions During Body Inspection: Dry						Right rear	3.7		mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
very minor	surface rust underbody	,				Suspension performance	~		
						Steering performance	~		+
						Shock absorbers	~		+
						Air Conditioning / Heater	•		
						Operation	~		Τ
Interior Comments						Electrical / Accessories	-		
Seats	Good					Head lights	~		Τ
	Card					Tail lights	~		+
Carpets	Good					Indicators	~		+
Panels	Good					Dashboard warning lights	~		+
Falleis						Wipers (front & rear)	~		
Dashboa	Ird Good					Window winder FL	~		+
						Window winder FR	~		+
<u>General</u> (<u>Comments</u>					Window winder RL	~		+
Drives well						Window winder RR	~		+
						Rear view mirrors	~		+
						Radio (basic test only)	~		+
						CD (basic test only)	<i>v</i> <i>v</i>		+
						Number of keys	1		L
Decal	ditions Dent - T	h Duite				Central locking	· ·		1
KOAG CON	ditions During Tes	L Drive:	Dry			Remote locking	~		+
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			<i>v</i> <i>v</i>
		•	-						
Inspecte	d by: Donovan Matar	a				Date: 03 Jul 202	4		
I have read	and understood th	is condition c	uide. Name:			Signature:			