

Report ID: 25,851,087 Version: 1 05 Jul 2024 Created:

Make:	Citroen	Model:	C5 Aircross	Body Style:	SUV		Pass	Fail	N/A
Year:	2019	Registration:	MGY527	Reg Expiry:	28 Oct 2024	Engine			
WoF Expiry:		Odometer:	76,895 Kms	Good No:	25851087	Oil level	~		
VIN:	VR7A45GFRKL041521	Next Service:	-,	Service Histor	y: No	Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty		6	Dente have a se		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	nical inspection prior to	purchase and th	nis can be arranged fo	or an additional	charge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	SC SC	-161-		Radiator / Hoses (visual)	~		
S = scratch	ATP.	A U			The second	Transmission			
D = dent	- HE			715		Operation	~		
R = rust PT = paint def				$\left[ \right] \left[ \right]$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HIG				거네니	CV joints	~		-
* = decals	- Alf			-Jul-	AID	Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs	$\neg \varnothing$	D SC SC	794	SC	Performance	~		
Dedulae		Note: som	ne defects & blemishe	s may not be dis	blayed in the diagram	Hand Brake	~		
BODY INS	pection Comments					Tyres (lowest observed tread	d depth	of tyre	1 2s)
						Left front	4		mm
						Right front		3	mm
						Left rear		3	mm
Conditions During Body Inspection: Wet						Right rear		3	mm
Conditions During Body inspection. Wet						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
No underb	ody inspection					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories	1		1
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ard					Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		•
Road Conditions During Test Drive: Dry						Central locking	~		
			•			Remote locking	~		
Engine Timing Mechanism: Unknown						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
	11 KA 11 14/11						4		
Inspecte	d by: Melissa Wilson					Date: 05 Jul 202	4		

I have read and understood this condition guide.

Name: .....

Signature: .....