

Basic Vehicle Condition Guide

Report ID: 25,853,500


Version: 2

Created: 21 Jul 2024

Make: Model: Isuzu D-MAX **Body Style:** Utility Year: 2017 Registration: KNQ973 Reg Expiry: 16 Sep 2024 WoF Expiry: **Odometer:** 18 Oct 2024 169,386 Kms **Good No:** 25853500 VIN: MPATFS85JHT006995 Next Service: 179000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Damage to Tub LR

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	marks, drivers split and hole		
Carpets	Average		
Panels	scuffs scratches marks		
Dashboard	scratches		

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Cleate	u. 2	1 701 20	727	
	Pass	Fail	N/A	
Engine		•		
Oil level	~			
Smoke & fumes	~			
Performance	V			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission			1	
Operation	~			
Noise	~			
Clutch	~			
CV joints	\(\times \)			
Wheel bearings	~			
Brakes			1	
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	l depth	of tyre	es)	
Left front	7	.0	mm	
Right front	8.0		mm	
Left rear	5.0		mm	
Right rear	6.0		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater			1	
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			
Wipers (front & rear)	~			
Window winder FL	~			
Window winder FR	~			
Window winder RL				
Window winder RR	\(\times \)			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	1	<u> </u>	1	
Central locking				
Certifian locking	~		1	
Remote locking	V V			
	<i>V</i>		~	

I have read and understood this condition guide.

Gary Adams

Name:

Signature:

09 Jul 2024

Reversing camera