

Report ID: 25,854,843 Version: 1 17 Jul 2024 Created:

Make:	Suzuki	Model:	Alto	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2012	<b>Registration:</b>	GHC764	<b>Reg Expiry:</b>	03 Jul 2024	Engine	1	L	1
WoF Expiry:	14 Mar 2025	Odometer:	68,065 Kms	Good No:	25854843	Oil level	~		
VIN:	MA3GFC31S00505148	Next Service:	76,000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
					C DT	Performance	~		
Key:	S SC	-0	S SD	-01-	S PT	Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust						Transmission			
						Operation	~		
PT = paint defe		F		$\left( \left  \left( \right) \right\rangle \right)$		Noise	~		
C = crack				+	S	Clutch	~		
P = pin dent	HID				게	CV joints	~		
* = decals	ssc 916			-No-	ELL'S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S S D						Performance	~		
Dadular		Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		+
body inspection comments						Tyres (lowest observed tread	•	oftvre	es)
Rear hatch struts weak									mm
						Right front		.0	mm
						Left rear		.0	mm
Conditions Duving Padu Inspection. Du						Right rear		.0	 mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments					Suspension				
	octane fuel	·				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
50005						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		-
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		$\left  - \right $
	I					Window winder FR	~		+
General Comments					Window winder RL	~		-	
Air conditioning and heating systems work fine at inspection time. Remote control taped up						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		+
						CD (basic test only)	~		
						Number of keys	2		L
Pood Conditions During Test Driver Day						Central locking	2 V		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
			11						
Inspected by: Gary Adams Date: 08 Jul 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....