

Report ID: 25,857,349 Version: 2 04 Jul 2024 Created:

Make:	Mazda	Model:	MPV	Body Style:	Wagon		Pass	Fail	N/A
Year:	2004	<b>Registration:</b>	GWL765	Reg Expiry:	13 Nov 2024	Engine	I		L
WoF Expiry:	08 Apr 2025	Odometer:	106,123 Kms	Good No:	25857349	Oil level	~		
VIN:	7AT0C11EX13402718	Next Service:	110,100km	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	S		S D S		S	Performance	~		
Key:	L'AL	=		502-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	scw			710	SCW	Operation	~		
PT = paint def	ect NP				70111	Noise	~		
C = crack					SC	Clutch			~
P = pin dent	sc dle				74116	CV joints	~		
*= decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv – signincan	W		D R PT		S W	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Rust hole in left front door						<b>Tyres</b> (lowest observed tread depth of tyres)			
Left rear view mirror scuffs						Left front	5	5	mm
Rust on the inside of both front doors Windscreen stone chips						Right front	4	1	mm
Boot sill rus	•					Left rear	e	5	mm
Conditions During Body Inspection: Dry						Right rear	2 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Underbody Front whee	surface rust					Suspension performance	~		
Front whee	anve					Steering performance	<		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
<sup>.</sup>						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Tes	t Drive:	Dry			Central locking	~		
- Fnaine Ti	ming Mechanism	Timing (	- Thain			Remote locking			~
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	огсант вен керіас	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Rowan Fey Date: 04 Jul 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....