

Report ID: 25,858,303 Version: 1 12 Jul 2024 Created:

Make:	Foton	Model:	Tunland	Body Style:	Utility		Pass	Fail	N/A
Year:	2016	<b>Registration:</b>	LSW473	Reg Expiry:	, 13 May 2025	Engine	1		
WoF Expiry:	11 Jul 2025	Odometer:	110,639 Kms	Good No:	25858303	Oil level	~		
VIN:	LVAV2MBB9FJ061492	Next Service:	120,633 Kms	Service Histor	Y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
			PP		S	Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	S PT SC			715	S SC W	Operation	~		
PT = paint def		F		$\left[ \left( \right) \right]$		Noise	~		
C = crack						Clutch	~		
P = pin dent	HID				74 <u>11</u>	CV joints			~
* = decals	sc 916			The second	ALC S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significan					S SC	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tyre	es)
						Left front	8.	0	mm
						Right front	8.	0	mm
						Left rear	5.	1	mm
Conditions During Body Inspection: Wet						Right rear	3.	3.4 m	
······································						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	11		1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
Partial servi	ce history					Window winder RR	~	_	
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	t Drive:	Wet			Central locking	~		
	-					Remote locking	~		
-	ming Mechanism:	Timing (				Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Hoani Saunders Date: 04 Jul 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....