


<b>Make:</b> Holden	<b>Model:</b> Colorado	<b>Body Style:</b> Utility
<b>Year:</b> 2011	<b>Registration:</b> FWF235	<b>Reg Expiry:</b> 17 Apr 2025
<b>WoF Expiry:</b> 02 Jul 2025	<b>Odometer:</b> 281,659 Kms	<b>Good No:</b> 26161732
<b>VIN:</b> MMMTFS85HBH5216	<b>Next Service:</b> 287,000 Kms	<b>Service History:</b> No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**  
 S = scratch  
 D = dent  
 R = rust  
 PT = paint defect  
 C = crack  
 P = pin dent  
 \* = decals  
 SC = stone chips  
 W = significant scuffs



Note: some defects & blemishes may not be displayed in the diagram

**Body Inspection Comments**  
 Moisture in left rear tail light  
 Stone chip in front windscreen

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**

**Interior Comments**

Seats	Average
Carpets	Average
Panels	Average
Dashboard	Dash loose on right side

**General Comments**  
 Check 4WD warning light on - 4WD module needed  
 Two key remotes, one remote isn't working. Keys don't lock or unlock doors. Interior central locking button works

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain  
 Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	6.1	mm	
Right front	6.1	mm	
Left rear	3.3	mm	
Right rear	3.8	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation		✓	
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)		✓	
CD (basic test only)		✓	
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Hoani Saunders Date: 11 Jul 2024

I have read and understood this condition guide. Name: ..... Signature: .....