

Basic Vehicle Condition Guide

Report ID: 26,166,204


Version: 2

Created: 22 Jul 2024

Make: Model: Volkswagen Golf **Body Style:** Wagon Year: 2005 Registration: HSG782 Reg Expiry: 12 Aug 2024 WoF Expiry: **Odometer:** 184,401 Kms **Good No:** 26166204 VIN: WVGZZZ1TZ5W17239 Next Service: 0 **Service History:** No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

RR tail light broken,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Inner CV boot centre needs replacing ,needs oil,minor coolant leak

| Interior Comments | | | |
|-------------------|---|--|--|
| Seats | wear,worn,minor stains , | | |
| Carpets | wear,minor stains , | | |
| Panels | hood lining and door trim cloth coming off, | | |
| Dashboard | Average | | |

General Comments

Inspected by:

Drives okay, needs a service,

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes

Donovan Matara

Kms: 74,062

| | Pass | Fail | N/A |
|------------------------------|---------------------------------------|---------|-----|
| Engine | | | |
| Oil level | | ~ | |
| Smoke & fumes | ~ | | |
| Performance | \(\triangle \) | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | | ~ | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | V | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | depth | of tyre | es) |
| Left front | 6 | .9 | mm |
| Right front | 6.9 | | mm |
| Left rear | 3.9 | | mm |
| Right rear | 6.5 | | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | \(\times \) | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | | ~ | |
| Electrical / Accessories | | | _ |
| Head lights | ' | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | | ~ | |
| Window winder RR | | ~ | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | > | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | ~ |
| | | | |

I have read and understood this condition guide.

Name:

Signature:

11 Jul 2024