

Basic Vehicle Condition Guide

Report ID: 26,169,206

Pass

~

~

/

V

1

Version: 6

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Operation

Noise

Clutch

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL

Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

04 Sep 2024 Created:

Fail

N/A

mm

mm

mm

 mm

5

3

1

/

/

/

1

1


1

Yes

Make: Model: Holden Colorado **Body Style:** Utility Year: 2018 Registration: LFB659 **Reg Expiry:** 26 Aug 2024 WoF Expiry: **Odometer:** 20 Feb 2025 220,724 Kms **Good No:** 26169206 VIN: MMU148EK0JH64028: Next Service: 235000 kms **Service History:** No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

RWD

<u>Interior Comments</u>				
Seats	OK			
Carpets	Average			
Panels	Average			
Dashboard	Good			

General Comments

Inspected by:

L/ front plastic side step crack

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Eleoit Kumar

Evidence of Cam Belt Replacement:

	Remote locking 🗸					
	Sat. Nav. (basic test only)		~			
Kms:	Reversing camera	'				
Date: 04 Sep 2024						
Name:	Signature:					

have read	and under	stand this	condition	aniide