


|                    |                   |                      |               |                         |             |
|--------------------|-------------------|----------------------|---------------|-------------------------|-------------|
| <b>Make:</b>       | Ford              | <b>Model:</b>        | Territory     | <b>Body Style:</b>      | SUV         |
| <b>Year:</b>       | 2014              | <b>Registration:</b> | HMR324        | <b>Reg Expiry:</b>      | 03 Jul 2024 |
| <b>WoF Expiry:</b> | 14 Jun 2024       | <b>Odometer:</b>     | 199,091 Kms   | <b>Good No:</b>         | 26171487    |
| <b>VIN:</b>        | 6FPAAAJGATDE52872 | <b>Next Service:</b> | 181,000 - Due | <b>Service History:</b> | Yes         |

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key:

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs



## Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

## Under Carriage & Under Bonnet Inspection Comments

Driveshaft Centre Bearing Bushing Torn

## Interior Comments

|           |                   |
|-----------|-------------------|
| Seats     | Drivers Seat Torn |
| Carpets   | Average           |
| Panels    | Front Panels Worn |
| Dashboard | Average           |

## General Comments

Creaking Noise from Rear  
Left Dip Headlight & Right Brake Light Out

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

|                                                     | Pass | Fail | N/A |
|-----------------------------------------------------|------|------|-----|
| <b>Engine</b>                                       |      |      |     |
| Oil level                                           | ✓    |      |     |
| Smoke & fumes                                       | ✓    |      |     |
| Performance                                         | ✓    |      |     |
| Noise                                               | ✓    |      |     |
| <b>Cooling System</b>                               |      |      |     |
| Coolant condition                                   | ✓    |      |     |
| Performance                                         | ✓    |      |     |
| Radiator / Hoses (visual)                           | ✓    |      |     |
| <b>Transmission</b>                                 |      |      |     |
| Operation                                           | ✓    |      |     |
| Noise                                               | ✓    |      |     |
| Clutch                                              |      |      | ✓   |
| CV joints                                           | ✓    |      |     |
| Wheel bearings                                      | ✓    |      |     |
| <b>Brakes</b>                                       |      |      |     |
| Performance                                         | ✓    |      |     |
| Hand Brake                                          | ✓    |      |     |
| <b>Tyres</b> (lowest observed tread depth of tyres) |      |      |     |
| Left front                                          | 7.0  | mm   |     |
| Right front                                         | 7.0  | mm   |     |
| Left rear                                           | 7.0  | mm   |     |
| Right rear                                          | 7.5  | mm   |     |
| Spare                                               | Yes  |      |     |
| <b>Suspension</b>                                   |      |      |     |
| Suspension performance                              | ✓    |      |     |
| Steering performance                                | ✓    |      |     |
| Shock absorbers                                     | ✓    |      |     |
| <b>Air Conditioning / Heater</b>                    |      |      |     |
| Operation                                           | ✓    |      |     |
| <b>Electrical / Accessories</b>                     |      |      |     |
| Head lights                                         |      | ✓    |     |
| Tail lights                                         |      | ✓    |     |
| Indicators                                          | ✓    |      |     |
| Dashboard warning lights                            | ✓    |      |     |
| Wipers (front & rear)                               | ✓    |      |     |
| Window winder FL                                    | ✓    |      |     |
| Window winder FR                                    | ✓    |      |     |
| Window winder RL                                    | ✓    |      |     |
| Window winder RR                                    |      | ✓    |     |
| Rear view mirrors                                   | ✓    |      |     |
| Radio (basic test only)                             | ✓    |      |     |
| CD (basic test only)                                | ✓    |      |     |
| Number of keys                                      | 1    |      |     |
| Central locking                                     | ✓    |      |     |
| Remote locking                                      | ✓    |      |     |
| Sat. Nav. (basic test only)                         | ✓    |      |     |
| Reversing camera                                    | ✓    |      |     |

Inspected by: Samuel Weir

Date: 15 Jul 2024

I have read and understood this condition guide.

Name: .....

Signature: .....