

Basic Vehicle Condition Guide

Report ID: 26,175,479


Version: 1

Created: 11 Jul 2024

Make: Model: Nissan Leaf **Body Style:** Hatchback Year: 2012 Registration: MGD758 Reg Expiry: 18 Jul 2025 WoF Expiry: **Odometer:** 114,759 Kms **Good No:** 26175479 VIN: 7AT0DH8KX19015435 Next Service: 0 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

•

| Interior Comments | | | |
|-------------------|--|--|--|
| Seats | minor stains , | | |
| Carpets | minor stains , | | |
| Panels | minor stains ,missing power cord and pack, | | |
| Dashboard | Good | | |

General Comments

Drives okay, needs a service, does have a red triangle light on dash not sure what it means

No home charging cable with this vehicle

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Donovan Matara Date: 11 Jul 2024

Name:

| | | _ | _ | |
|--|------------|----------|-----|--|
| | Pass | Fail | N/A | |
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | <i>y y</i> | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | <i>v</i> | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | 2 | .5 | mm | |
| Right front | 5.1 | | mm | |
| Left rear | 5.5 | | mm | |
| Right rear | 3.3 | | mm | |
| Spare | | N/A | | |
| Suspension | • | | | |
| Suspension performance | ~ | | | |
| Steering performance | V | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | | ~ | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | ~ | | | |
| Window winder FR | ~ | | | |
| Window winder RL | V | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 1 | <u> </u> | - | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | ~ | | | |
| · | | <u> </u> | | |

Signature: