

Noto: This you out is not		Performance	~	
<b>Note: This report is not a warranty</b> This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.		Noise	~	
		Cooling System		
a full mechanical inspec	tion phor to purchase and this can be arranged for an additional charge.	Coolant condition	~	
		Performance	~	
Key:		Radiator / Hoses (visual)	~	
S = scratch D = dent R = rust PT = paint defect		Transmission		
		Operation	<b>v</b>	
		Noise	~	
C = crack	SPT	Clutch		~
P = pin dent		CV joints	~	-
* = decals S SC		Wheel bearings	· ·	
SC = stone chips		Brakes	-	
W = significant scuffs S		Performance	<b>~</b>	
	Note: some defects & blemishes may not be displayed in the diagram	Hand Brake	~	
Body Inspection C	Tyres (lowest observed tread depth of tyres)			
Tint bubbling up on boot windows		Left front	4	mm
		Right front		
		Left rear	4	mm
			5	mm
Conditions During Body Inspection: Dry		Right rear	5	mm
Under Carriage & Under Bonnet Inspection Comments		Spare Yes		
<u>onder Camage &amp; </u>	bilder bonnet inspection comments	Suspension		
		Suspension performance	~	
		Steering performance	~	
		Shock absorbers	~	
		Air Conditioning / Heater		
		Operation	~	
Interior Comments		Electrical / Accessories		
Seats	Good	Head lights	~	
Corpote	Good	Tail lights	~	
Carpets		Indicators	~	
Panels	Good	Dashboard warning lights	~	
	Good	Wipers (front & rear)	~	
Dashboard		Window winder FL	~	
		Window winder FR	~	
General Comments		Window winder RL	~	
Vehicle drove well		Window winder RR	~	
		Rear view mirrors	~	
		Radio (basic test only)	~	
		CD (basic test only)		~
		Number of keys	1	
Road Conditions During Test Drive: Dry		Central locking	~	
,		Remote locking	~	_
Engine Timing Mee	Sat. Nav. (basic test only)		~	
Evidence of Cam Belt Replacement: Yes Kms: 167,000		Reversing camera	~	
		Ĺ		
Inspected by: Jay	den Roxburgh	Date: 26 Jul 2024	4	

Name: .....

I have read and understood this condition guide.

.....

Signature: .....

 Report ID:
 26,179,638

 Version:
 2

 Created:
 26 Jul 2024

Pass

V

V

Fail

N/A