

Report ID: 26,182,373 Version: 2 22 Nov 2024 Created:

Make: Subaru Model: Outback Body Style: Wagon	Pass F	ail N/A
Year: 2014 Registration: Reg Expiry: Engine		
WoF Expiry: 28 Aug 2025 Odometer: 90,637 Kms Good No: 26182373 Oil level	~	
VIN: 7AT0GF16X24004294 Next Service: 100,000 Kms Service History: No	~	
Performance	~	
Note: This report is not a warranty	· ·	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends Cooling System	V	
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.	~	
Performance	~ ~	
Key:	~ ~ ~	
S = scratch	V	
D = dent D = virt	~	
PT = paint defect C = crack		
P = pin dent CV joints	~	
* = decals Wheel bearings	-	
SC = stone chips	~	
W = significant scuffs Performance		
Note: come defects % blemiches may not be displayed in the disprese	~	
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram Hand Brake		
Tyres (lowest observed tr		-
Left front	2.5	mm
Right front	2.5	mm
Left rear	4.0	mm
Conditions During Body Inspection: Dry Right rear	3.5	mm
Under Carriage & Under Bonnet Inspection Comments Suspension	N/A	
	-	
Suspension performance		
Steering performance	~	
Shock absorbers	~	
Air Conditioning / Heate	•	
Interior Comments	~	
Seats	~	
Carpets Good Tail lights	~	
	~	
Panels Good Dashboard warning ligh		
Dashboard Good Wipers (front & rear)	~	
	~	
Window winder FR	~	
General Comments Window winder RL	~	
Window winder RR	~	
Rear view mirrors	~	
Radio (basic test only)	~	
CD (basic test only)	~	
Number of keys	1	
Road Conditions During Test Drive: Dry Central locking	~	
Remote locking	~	
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only		~
Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera	~	
Inspected by: Lewis Dolamore Date: 29 Aug	2024	

I have read and understood this condition guide.

Name:

Signature: