

Basic Vehicle Condition Guide

Report ID: 26,184,422


Version: 1

Created: 18 Jul 2024

Make: Model: Holden Commodore **Body Style:** Sedan Year: 2017 Registration: KYE467 Reg Expiry: 02 Oct 2023 WoF Expiry: **Odometer:** 07 Feb 2024 202,425 Kms **Good No:** 26184422 VIN: 6G1FA5E58HL322125 Next Service: 0 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Missing rear spoiler

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Left front lower arm rubber joint leaking grease.

| <u>Interior Comments</u> | | | |
|--------------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

No antifreeze in coolant ,bonnet strut worn , needs fixing . Drivers seat belt buckle broken, missing plastic cover.

Faulty stereo screen, display does not light up sometimes and comes on and off.

Volume button on steering wheel not working

Ac 8c ,heater 40 c

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: **Timing Chain**

Evidence of Cam Belt Replacement: Not Applicable Kms:

18 Jul 2024 Inspected by: Allan Young Date:

Name:

| | Pass | Fail | N/A |
|------------------------------|--------------|---------|-----|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | ~ | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | | ~ | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | | | ~ |
| Wheel bearings | ~ | | |
| Brakes | | • | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | | 5 | mm |
| Right front | 5 | | mm |
| Left rear | 8 | | mm |
| Right rear | 8 | | mm |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | \(\times \) | | |
| Window winder FL | ~ | | |
| Window winder FR | V | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | | | ~ |
| Number of keys | 1 | | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | V | | |

Signature: