

Report ID: 26,189,536 4 Version: 12 Dec 2024 Created:

Make:	Nissan	Model:	X-Trail	Body Style:	SUV		Pass	Fail	N/A
Year:	2008	<b>Registration:</b>	EMG204	Reg Expiry:	27 Nov 2024	Engine	1	I	1
WoF Expiry:	23 Sep 2024	Odometer:	259,431 Kms	Good No:	26189536	Oil level	~		
VIN:	JN1TANT31A0000618	Next Service:	260,320kms	Service Histor	<b>y:</b> No	Smoke & fumes	~		-
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tr	his can be arranged to	or an additional of	inarge.	Coolant condition	~		
	S SC S		SP SD	S	S	Performance	~		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
R = rust	S PT C SC W	S PT	Operation		~				
PT = paint defe	ect NP				1111	Noise	~		
C = crack				TTV.	S SC W	Clutch			~
P = pin dent	s sc dl				2414	CV joints	~		
* = decals		10		10	ED S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	SC		S W S P	S	S	Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishe	s may not be disp	blayed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	4.0 m		mm
						Right front	4	.0	mm
						Left rear	3	.2	mm
Conditions During Body Inspection: Dry						Right rear	4.0 mm		mm
						Spare Yes			
Under Ca	rriage & Under Bor	net Inspectio	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Commonte						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		<u> </u>
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		<u> </u>
Dashboa	rd Good					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		─
Concrol	ommonts					Window winder FR	~		<u> </u>
<u>General Comments</u>						Window winder RL	~		<u> </u>
Transmission not functioning correctly						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
Engine Tir	ming Mechanism	Timing				Remote locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
	or carri bert nepiac			NIII <b>3</b> ,		Reversing camera			~
Inspected	d by: Chad Nicholas					Date: 29 Oct 202	24		
· · · · ·									

I have read and understood this condition guide.

Name: .....

Signature: .....