

Report ID: 26,192,418 Version: 2 21 Aug 2024 Created:

| Make: | Nissan | Model: | Urvan | Body Style: | Van | | Pass | Fail | N/A |
|--|---------------------------|----------------------|------------------------|--------------------|----------------------|--|--------|----------|-----|
| Year: | 2013 | Registration: | GYS529 | Reg Expiry: | 07 Jan 2025 | Engine | 1 | <u> </u> | I |
| WoF Expiry: | | Odometer: | 159,203 Kms | Good No: | 26192418 | Oil level | ~ | | |
| VIN: | JN1MG2E25Z0760729 | Next Service: | 169000 | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | V | | |
| | port is not a warranty | pration is made | for age and mileage | Parts have not | been dismontled or | Noise | r | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | lical inspection prior to | purchase and th | his can be arranged fo | or an additional o | charge. | Coolant condition | ~ | | |
| | | | S | | | Performance | ~ | | |
| Key: | | -0 | | | | Radiator / Hoses (visual) | ~ | | |
| S = scratch D = dent | | | | | | Transmission | | | |
| R = rust | | | | 210 | HIVS | Operation | ~ | | |
| PT = paint defe | ect NP | | | | 10111 | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | HIP | | | | 24116 | CV joints | ~ | | |
| * = decals | - Alt | 10 | | 10 | | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| W = significan | | | S | | | Performance | ~ | | |
| Body Inst | pection Comments | Note: som | ne defects & blemishes | s may not be disp | layed in the diagram | Hand Brake | ~ | | |
| | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front | 6 | .0 | mm |
| | | | | | | Right front | 6 | .0 | mm |
| | | | | | | Left rear | 8 | .0 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 8.0 mn | | mm |
| | | | | | | Spare | Yes | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| Interior Comments | | | | | | Operation 🖌 | | | |
| Interior Comments Average | | | | | | Electrical / Accessories | | | |
| Seats | Average | | | | | Head lights | ~ | | |
| Carpets | Average | | | | | Tail lights | ~ | | |
| | Average | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| Dashboa | Average | | | | | Wipers (front & rear) | ~ | | |
| | | | | | | Window winder FL | ~ | | |
| Concrol | | | | | | Window winder FR | ~ | | |
| | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| . | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 1 | | |
| Road Con | ditions During Test | Drive: | Dry | | | Central locking | ~ | | |
| Engine Tir | ming Mechanism | Timing | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Sat. Nav. (basic test only) | | | ~ |
| | | | lot Applicable | 11115. | | Reversing camera | | | ~ |
| Inspected by: John Jones Date: 23 Jul 2024 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: