

Report ID: 26,193,826 2 Version: 12 Dec 2024 Created:

Make:	Subaru	Model:	Impreza	Body Style:	Wagon		Pass	Fail	N/A
Year:	1998	Registration:	Impreza EBJ381	Reg Expiry:	wagon 26 Sep 2024	Engine	1 0 3 5	ı all	
WoF Expiry:		Odometer:	225.870 Kms	Good No:	26 Sep 2024 26193826	Oil level	~		T
VIN:	7A8GF090707048508			Service Histor		Smoke & fumes	<i>v</i> <i>v</i>		+
	78891090707048508	Next Service.	232000	Service mistor	y. NO	Performance	v v		+
	port is not a warranty					Noise	~		<u> </u>
	a guide only. Conside sting undertaken. The					Cooling System	V		
	ical inspection prior to					Coolant condition			T
						Performance	~		<u> </u>
Key:	SC W	0	P SC P		Р	Radiator / Hoses (visual)	~		
S = scratch						Radiator / Hoses (visual)			
D = dent	scw Alt				HID DPT				T
R = rust				10	SHIK	Operation	~		+
PT = paint def	ect			+	PT	Noise Clutch	~		
C = crack P = pin dent	Ht			-			~		
* = decals	sc dr				ELA SD	CV joints	~		
SC = stone chips						Wheel bearings	~		
W = significant scuffs SC W SC S SC W P SC						Brakes			
						Performance	~		—
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake			Ļ
Rear left jacking point dented							vres (lowest observed tread depth of tyres)		
incut iere jue	g ponte de ned					Left front	6	.0	mm
						Right front	6	.0	mm
						Left rear	5.	.0	mm
Conditions During Body Inspection: Dry						Right rear	5	.0	mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
<u>Under Ca</u>	irriage & Under Bor	inet inspectic	on comments			Suspension			
						Suspension performance	~		<u> </u>
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater		1	
Interior Comments						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	ard Assessed					Wipers (front & rear)	~		
Dashbud	ard Average					Window winder FL	~		<u> </u>
						Window winder FR	~		
<u>General</u>	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
F. • =:						Remote locking	~		
-	ming Mechanism:	Cambel				Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
Inspected by: Sione Mae						Date: 20 Jul 2024			
inspecte	u by: Sione Mae					Date: 20 Jul 202	7		
I have read	and understood th	is condition o	uide Name [.]			Signature:			

I have read and understood this condition guide.

Name: